Work Orde <i>July 6, 2010 2:5</i>		365									Page 1
Revision ID:	D412-724-04 Head Rest Ass			Accept				S	Setup Star		
	7/06/10	Start Qty: 2.00 Req'd Qty: 2.00			Cust Iter Custome						
Approvals:	Process Pla	nn: CZ	Date: 16/7/6	Tooling: SPC (Y/N):		Date:		F	Run Star Sto		
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Tool II	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr		vision Nbr									
DC Document Control			DL 1-044 is a W/O on it's own,[724-044 CHG001	0.00 0.00 Photocopy bluefile and	d create labels per	8,8(05)	126	*	ON B	G lo-	8-25
Packaging Packaging		Pick Kit Memo		0.00				10/2	Stry	S	1 Ex

120 QC

Quality Control

QC4- 100% Inspect kits for completeness

Memo

Dart Aerospace Ltd

Dail Ae	ospace	Liu							
W/O:			WO	RK ORDER CHANGES					
DATE	STEP	PRO	OCEDURE CHAN	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						,			
					1				
Part No	:	PAR #:	Fault Categ	gory: N	ICR: Yes	No DQ	A:	_ Date: _	
	Re	solution:	Disposition	n: C	A: N/C CI	osed:		Date: _	
NCR:			WORK ORDE	ER NON-CONFORMANO	CE (NCR	1)			
DATE	STEP	Description of NC		0: 0		cation	Approval	Approval	
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sect	ion C	Chief Eng	QC Inspector
								1	
						-			
1	1								

NOTE: Date & initial all entries

Work Order ID 60365



Page 2

July 6, 2010 2:57:24 PM

Required Date: 7/20/10

Item ID:

D412-724-044

Accept

Date:

Date:

Setup Start

Stop

Revision ID:

Start Date:

Item Name:

Head Rest Assembly, RH

7/06/10

Start Oty: 2.00

Req'd Qty: 2.00

Date:

Cust Item ID:

Customer:

Reference:

Approvals:

Process Plan:

Date:

SPC (Y/N):

Tooling:

0.00

0.00

Set Up/

Run Hours

Tool ID

Tool # Plan Code

Accept Otv

Reject Otv

Reject Number

130

Sequence ID/

Work Center ID

Packaging

Packaging

Packaging

Operation

Description

Memo

Identify and pack for shipping as per PPP 044□Location:

140

OC

Quality Control

OC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Run

Start



Stop

Insp.

Stamp

Dart Aerospace Ltd

W/O:		WORK ORDER CI	HANGES				
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						<u> </u>	
Part No	:	PAR #: Fault Category:	NCR: Yes	No DQ	A:	Date: _	

Resolution:			Dispositio	n:	QA: N/C Clos	sed:	Date:			
NCR:			WORK ORDER NON-CONFORMANCE (NCR)							
		Description of NC		Corrective Action Section	on B	Verification	Approval Chief Eng	Approval QC Inspector		
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C				
							1			
-		<u> </u>								
•										
• •										
NOTE: D	ate & initia	al all entries								

Picklist Print

July 6, 2010 2:57:23 PM

Work Order ID: 60365

D412-724-044 Parent Item:

Parent Item Name: Head Rest Assembly, RH



Start Date: 7/06/10

Start Qty: 2.00

Required Date: 7/20/10

Page 1

Required Qty: 2.00

ርո	m	m	en	te:

IPP Rev:A□04.09.08□New Issue□KJ/JLM

Comments:	IPP Rev:A \ 04.09.0	Journey Issueur.	J/JLIVI										
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
AN525-10R6 2		Purchased	No			120	Each	212.0000		s lel c	ry sf		
				Location	!	Loc	<u>Oty</u>	Loc Code				1	
				ST325			212		car.		_		
<i>N</i>					113524		212		8		_		. 1
D3303-041	#### ####	Manufactured	No			120	Each	0.0000	1 	a^2 .	\sim		V/2-2-0/
	81111 8 1111 1181 1181									560	863	10/	812581
† Head Rest			Ma			120	Each	11,0000	1 .				1
D3304-044	SCIII BIBII BIBI ISCI	Manufactured	No			120	Each	11.0000		2	1/	1	
							ı			/	· & / 8%	124	5/_0
Tube Assembly				Location		Loc	Oty	Loc Code		/			
				ST187	<u> </u>	Loc	11	Loc Coue		_			
				31107	44356		1			1.	_		
				~_	54443		10		_				

Dart Ae	rospace L	.td							
W/O:			WC	RK ORDER CHANG	ES				
DATE	STEP	PRO	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
			Market and the second s						
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	_ Date: _	
	Res	solution:	Disposition	n:	_ QA: N/C C	closed:		Date: _	
NCR:		1	WORK ORDI	ER NON-CONFORMA	ANCE (NC	R)			
		Description of NC		Corrective Action Sect	ion B	Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sect	ion C	Chief Eng	QC Inspector
•									
						1			

DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
							·	

NOTE: Date & initial all entries

REFERENCE ONLY

3.0 INSTALLATION PROCEDURE

To install a Dart Head Rest Assembly:

- If installed, remove the existing Head Rest Assembly by pulling the quick release pin that attaches it to the seat. Make note of the installation position (if applicable).
- Inspect the seat for damage in the vicinity of the Head Rest Assembly. Consult the Aircraft Maintenance Manual for disposition if damage is observed.
- If only replacing the Head Rest with the equivalent Dart D3303-041 Head Rest, separate the existing Head Rest from the existing Tube Assembly by undoing 4 screws. Re-assemble D3303-041 Head Rest with existing Tube Assembly by installing 4 screws and tightening to 15-25 in lb.
- If only replacing the Tube Assembly with a Dart D3304-041/-043/-044 Tube Assembly, separate the existing Head Rest from the existing Tube Assembly by undoing 4 screws. Re-assemble existing Head Rest with Dart D3304-041/-043/-044 Tube Assembly by installing 4 screws and tightening to 15-25 in lb.
- Slide the new or modified Head Rest Assembly into the seat tube and lock in place at the same location that the old Head Rest Assembly was installed (if applicable) using the quick release pin. Ensure pin is properly engaged.

4.0 WEIGHT AND BALANCE

There is negligible weight change associated with the installation of the Dart Head Rests.

5.0 PARTS LIST

QTY -011	QTY -041	QTY -043	QTY -044	Part Number	Description
Х			<u> </u>	D412-724-011	Dart Replacement Head Rest Kit, for 205/212/412
2	х			D412-724-041	Head Rest Assembly, Center
1		х		D412-724-043	Head Rest Assembly, LH
1			Х	D412-724-044	Head Rest Assembly, RH
				D0000 044	Head Rest
	1	1	1 1	D3303-041	
	1			D3304-041	Tube Assembly
		1		D3304-043	Tube Assembly
			1	D3304-044 .	Tube Assembly
	4	4	4	AN525-10R6	Screw